



Facilities Comprehensive Inspection Report

General Site Information		
Location	Dromore Park /Pavilion	Date: Jan 25, 2020
Inspector:	Kevin Green Facilities Manager	

Pavilion Information		
Address:	Southgate #224240 Dromore	
Site Location:	Main Intersection Concession 18 (Egremont) and Grey County Road 23	
General Information	Capacity Open	Size:
		
Structure:	Materials: Screenings Base Steel Roof Framed Roof Wood Frame	Amenities: 8- Picnic Tables
	Perimeter: Concrete Walkway Gravel/ Screenings Grass area	Activities: Located in Municipal Park Playground Sport Court Ball Diamond Soccer Field
Kitchen: No		

**TOWNSHIP OF SOUTHGATE
RECREATION**

550 Main St. E Dundalk ON N0C 1B0

Kevin Green, Facilities Manager



Phone: (519) 923-3431

Toll Free: (888) 560-6607

Web: www.southgate.ca

e-mail: kgreen@southgate.ca

Facility Inspection Report:		
Reference:	Issue:	Date Repair
	Tires and surfacing upgrade	
	Surface area improved	
	Shade improvement Planted trees November	

Projected 5-year capital expenditure:

Nothing current