



## Facilities Comprehensive Inspection Report

General Site Information		
Location	Joe Lisanti Park	Date: Jan, 2020
Inspector:	Kevin Green Facilities Manager	

Park Information		
Address:	39 Sinclair St Dundalk On	
Site Location:	Main Intersection Sinclair St and Main St Dundalk	
General Information	Subdivision Park	Size: N/A
		
<b>Structure:</b>	Materials:	<b>Amenities:</b> ?- Picnic Tables  <b>Activities:</b> Located in Municipal Park Playground
	Perimeter: Screenings Walkway Grass area	

**TOWNSHIP OF SOUTHGATE  
RECREATION**

550 Main St. E Dundalk ON N0C 1B0

Kevin Green, Facilities Manager



**Phone:** (519) 923-3431

**Toll Free:** (888) 560-6607

**Web:** [www.southgate.ca](http://www.southgate.ca)

**e-mail:** [kgreen@southgate.ca](mailto:kgreen@southgate.ca)

<b>Facility Inspection Report:</b>		
Reference:	Issue:	Date Repair
	Install shade structure  Trees Planted 2014	As funds become available
	Age appropriate play structure 5 and under	As funds become available
	Fencing	<5 years

**Projected 10-year capital expenditure:**

- Shade Structure