





Facilities Comprehensive Inspection Report

General Site Information		
Location	Dundalk Olde Town Hall	Date: Jan, 2020
		Temperature: 5 degrees
Inspector:	Kevin Green Facilities Supervisor	Weather: Cloudy

Surface Information		
Address:	90 Main St	
Site Location:	Main St E and Artemesia St Dundalk	
General Information	Not Accessible	Size:
		
Structure:	Materials: Stone Foundation Wood Frame Shingled Roof Wood Interior Walls Wood Core Exterior Doors Glass Main Entrance	Amenities: Theatre Seating 216 Chair Lift 2- Office spaces Rented Activities:
	Perimeter: Concrete Walkway Inter Locking Brick Grass area	
Kitchen: Yes	Stove /Refrigerator	



Facility Inspection Report:		
Reference:	Issue:	Reference
	Applied Grant for renovation. If grant unsuccessful next step demolition	

Projected 5-year capital expenditure:

- Renovation

Supporting Documents: