



Facilities Comprehensive Inspection Report

General Site Information		
Location	Pat Dales Park	Date: Jan, 2020
Inspector:	Kevin Green Facilities Manager	

Park Information		
Address:	550 Main Street E Dundalk On	
Site Location:	Main Intersection Sinclair St and Main St Dundalk	
General Information	Community Park	Size: N/A
		
Structure:	Materials:	Amenities: ?- Picnic Tables Activities: Located in Municipal Park Playground Ball Park
	Perimeter: Grass area	



Facility Inspection Report:		
Reference:	Issue:	Date Repair
	Replace row of Ash trees lost	2020
	No structural issues	

Projected 5 year capital expenditure:

- Tree planting