




Facilities Comprehensive Inspection Report

General Site Information		
Location	Proton Station Park	Date: Jan, 2020
Inspector:	Kevin Green Facilities Manager	

Park Information		
Address:		
Site Location:	Main Intersection Southgate 26 and Southgate Side Road 73	
General Information	Community Park	Size: N/A
		
Structure:	Materials:	Amenities: ?- Picnic Tables Activities: Located in Municipal Park Playground Ball Park
	Perimeter: Grass area	



Facility Inspection Report:		
Reference:	Issue:	Date Repair
	Playground surface material	2020

Projected 10-year capital expenditure:

- Shade Structure
- Surplus land

Supporting Documents/ Inspections: